

SECRET

PRIORITY

29 NOV 1963

P 271734Z
FM CIA WASHDC
TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB
RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA
RUCVAB/2D RTS, BARKSDALE AFB, LA
RUEAHQ/DIAXX
RUECYG/NAVY PIC
RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF
RUWGAA/2AF, BARKSDALE AFB, LA
DA GRNC
BT
SECRET

OUT 52375

1963 NOV 27 20 40Z

CITE CIA-Z-1041

H
C
C
I
A

15TH AF (FOR DI); SAC (FOR DIM, GOLDEN TREE, DOCR, DM 4)

2D AF (FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

Grace (File)

1. CAMERA B 8 WAS USED IN MISSION 3778 FLOWN ON 21 NOVEMBER 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINUS DENSITY DOTS ARE NUMEROUS AND PRONOUNCED ON THE FIRST 50 PER CENT OF THE MISSION AND BECOME FAINT AND LESS NUMEROUS ON THE REMAINDER. OUTBOARD EDGE FOG APPEARS INTERMITTENTLY THROUGHOUT THE MISSION. THE TITLING IS BADLY SMEARED ON FRAMES 147-150. A MANUFACTURING SPLICE ON FRAME 1972 IS ASSOCIATED WITH HEAVY CREASES THROUGH FRAME 2004.

C. 9L SIDE: REPAIRED TEARS APPEAR ON FRAMES 300, 306, 307 AND 976. THERE ARE SEVERAL RANDOM CREASES ON FRAME 303.

Declassification Review by NGA/DoD

SECRET

Excluded from automatic
downgrading and
declassification

A MANUFACTURING SPLICE ON FRAME 986 IS ASSOCIATED WITH CREASES ON FRAMES 986 AND 987.

D. BOTH SIDES: PROCESSING STREAKS, PINHOLES, BLISTERS, EMULSION GOUGES, AND HANDLING MARKS ARE MINOR AND INTERMITTENT THROUGHOUT THE MISSION. THE METERING IS SLIGHTLY ERRATIC. THERE ARE 2199 FRAMES ON EACH SIDE OF THE MISSION.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALITIES.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 75 PER CENT OF THIS MISSION. SCP-1

S E C R E T

-END OF MESSAGE-

(ALSO PASSED TO CIA WATCH (CGS))